

# Liquid Oxygen Cylinder Explosion

---

- **Improper methods used to render scrap cylinder unserviceable**
- **Unsafe modifications to cylinder design**

The incident described in the following presentation did not involve an Airgas company.

# Accident Profile

---

- Two individuals (ages 42 and 60) found a liquid oxygen cylinder that had been removed from service and left at a scrap metal dealer
- The individuals were self-employed in scrap metal cutting operations and intended to use the cylinder in their work

# Accident Profile

---

- The individuals had access to a liquid oxygen supplier where cylinder ownership would not be questioned
- Jury-rigging fill connections, the first attempt to fill the cylinder resulted in rapid venting through the Pressure Relief Device (PRD)

# Accident Profile

---

- The PRDs were removed and plugged
- The cylinder was filled while onboard a pickup truck
- The cylinder, which had no vacuum, was now unable to vent excess pressure

# Accident Profile

---

- While being transported down a busy highway, the pickup truck experienced a flat tire
- Shortly thereafter, the cylinder exploded with the results shown in the following slides

# Pickup truck on which the cylinder was being transported

---



# Pickup truck on which the cylinder was being transported

---





# Pickup and cylinder remains

---





# Cylinder top

---



# Cylinder outer shell, bottom

---



# Cylinder bottom shell

---






PRD location was plugged using a threaded cap

---






Plug/Cap

Hole in  
vacuum port

Both inner and outer shells separated at bottom welds

---





Cylinder exploded at 12:40 PM while transport vehicle was parked on busy Interstate highway




The blast blew one individual across 5 lanes of traffic. The other was blown approximately 40 feet. Both survived

---



Cylinder flew approximately ¼ mile before plunging through the roof of an apartment, severing a main natural gas line and coming to rest in the living space

---



Despite heavy damage, no injuries to apartment tenants were reported

---






# Apartment interior

---



Note that the media reported the event as a  
Butane cylinder explosion

---



**Butane explosion on I-10  
hurts two, hits apartment**